



Errata

2

Manual: 27784

Manual Index: 01

Table of Contents:

- 1. *Reference: Page 1 - 10, Chapter 1.6, Table 1-3..... 2 - 3*



This page has been intentionally left blank.





1. Reference: Page 1 - 10, Chapter 1.6, Table 1-3

The referenced information (table) is revised as follows.

The table row:

PCI Interface	VI/O voltage is neither relevant nor used
---------------	---

is changed to read:

PCI Interface	Universal; 3.3V (5V-tolerant); the VI/O pins are not connected
---------------	--



This page has been intentionally left blank.

